


# IMPORTANT

## Part numbers 700822 and 800822

The drive ears on the pressure plate must line up with the reliefs slots in the flywheel. If they are not aligned properly, the clutch will slip and prematurely wear out.

**INSTALL CLUTCH HARDWARE AS SHOWN**  
PLEASE CALL OUR TECH LINE IF YOU HAVE ANY QUESTIONS



"NOTE" Centerforce tip sheets are for general reference only. Please refer to your owners manual for vehicle specifications.

# IMPORTANT